



Ultrasonic Welder with a 20 inch Reach

Do you need a 20" stroke actuator?



Stroking a horn 20" is sometimes needed if welding into a hard to reach area or in this case, a part that can not be unloaded with a 6" stroke actuator in the way.



This standard actuator was mounted on a slide with 16" of stroke. The actuator is first lowered into position and then the horn extends to weld. This machine welds an ice chute to the inside of a freezer door.